

Hormead Parish

Update on My Work – for October 2018

Dawn Grocock - HCC Access Projects Officer

New problem or change to current problem action

Path number	Path Status	Problem	Current Action	Database no. & action summary
6	BOAT	Surface of route too narrow for vehicles, due to ditches and drainage features	Believe has historically been narrow, as old trees in hedge line. Ditches at the sides do not look new either. Culvert's brick headwalls do need replacing though, so can see if possible to widen then. Will need approval from Flood and Water Team though, met on site to discuss.	10207700 In progress
13	FP	Path ploughed and not reinstated	inspected, need to contact landowner, although low priority as currently recorded as dead end route	10207110
18	FP	Obstruction	Awaiting confirmation from Definitive Map team as some of the fencing could be over the DM path line	10206889 10207112 In progress
21	FP	Path ploughed and not reinstated	Contacted landowner	10204401
28	FP	Signpost on road overgrown with scrub	Have asked CMS vols to clear, works carried out	10207890 Done
28	FP	Waymark post needed beyond farm yard	DM line not, as walked on ground. Looking to clear and mark DM line. Letter to be sent to landowner explaining and CMS vols asked to install, works carried out	10207891 Done
28	FP	overgrown	DM line not, as walked on ground. Looking to clear and mark DM line. Letter to be sent to landowner explaining and CMS vols asked to clear, works carried out	10207771 10207892 Done