

Horme ad Parish

Update on My Work – for March 2019

New problem or change to current problem action

Path number	Path Status	Problem	Current Action	Database no. & action summary
6	BOAT	Surface of route too narrow for vehicles, due to ditches and drainage features	Believe has historically been narrow, as old trees in hedge line. Ditches at the sides do not look new either. Culvert's brick headwalls do need replacing though, so can see if possible to widen then. Will need approval from Flood and Water Team though, met on site to discuss.	10207700 <b>In progress</b>
13	FP	Sign has been hit and at an angle. Righted now, but investigation needed at base to see if damage	Not damaged, but still leaning a bit, work on order	10209431 on order
13	FP	Steps improvements and handrail requested	Will ask vols or contractor to quote for works, work on order	10209497 <b>on order</b>
18	FP	Obstruction	Awaiting confirmation from Definitive Map team as some of the fencing could be over the DM path line	10206889 10207112 <b>In progress</b>
21	FP	Path ploughed and not reinstated	Contacted landowner	10204401