

Update on My Work in Hormead Parish – for February 2018

Dawn Grocock

Countryside Access Officer, Public Rights of Way Service

Path	Status	Problem	Current Action	Hermis / Confirm no.
6	BOAT	Surface of route too narrow for vehicles, due to ditches and drainage features	Believe has historically been narrow, as old trees in hedge line. Ditches at the sides do not look new either. Culvert's brick headwalls do need replacing though, so can see if possible to widen then. Will need approval from Flood and Water Team though.	10207700 In progress
13	FP	Path ploughed and not reinstated	inspected, need to contact landowner, although low priority as currently recorded as dead end route	10207110
13	FP	Steps are difficult and need a handrail	Possible P3 grant application for works from the PC, current slabs on steps loose, so asked CMS vols to make safe at the moment	10207111 In progress
18	FP	Obstruction	Awaiting confirmation from Definitive Map team as some of the fencing could be over the DM path line	10206889 10207112 In progress
21	FP	Path ploughed and not reinstated	Contacted landowner	10204401
28	FP	Signpost on road overgrown with scrub	Have asked CMS vols to clear	10207890 on order
28	FP	Waymark post needed beyond farm yard	DM line not, as walked on ground. Looking to clear and mark DM line. Letter to be sent to landowner explaining and CMS vols asked to install	10207891 on order
28	FP	overgrown	DM line not, as walked on ground. Looking to clear and mark DM line. Letter to be sent to landowner explaining and CMS vols asked to clear	10207771 10207892 on order